

L Number	Hits	Search Text	DB	Time stamp
-	0	enright-marybeth	USPAT; US-PGPUB	2003/12/17 18:53
-	313	steering near column same ignition near switch	USPAT; US-PGPUB	2003/12/16 23:25
-	12	steering near column same mounted same left same ignition near switch	USPAT; US-PGPUB	2003/08/07 22:49
-	12	steering near column same mounted same right same ignition near switch	USPAT; US-PGPUB	2003/08/07 22:31
-	9	(steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch)	USPAT; US-PGPUB	2003/08/07 22:31
-	3	(steering near column same mounted same right same ignition near switch) not ((steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch))	USPAT; US-PGPUB	2003/08/07 22:31
-	3	(steering near column same mounted same left same ignition near switch) not ((steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch))	USPAT; US-PGPUB	2003/08/07 22:31
-	3	((steering near column same mounted same right same ignition near switch) not ((steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch))) not ((steering near column same mounted same left same ignition near switch) not ((steering near column same mounted same left same ignition near switch) and (steering near column same mounted same right same ignition near switch)))	USPAT; US-PGPUB	2003/08/07 22:31
-	1	steering near column with mounted with left with ignition near switch	USPAT; US-PGPUB	2003/08/25 00:29
-	0	steering near column with mounted with right with ignition near switch	USPAT; US-PGPUB	2003/08/07 22:51
-	6	steering near column with left with ignition near switch	USPAT; US-PGPUB	2003/08/07 22:54
-	4	steering near column with right with ignition near switch	USPAT; US-PGPUB	2003/08/07 22:52
-	0	steering near column with left with right with ignition near switch\$1	USPAT; US-PGPUB	2003/08/07 22:54
-	20	steering near column with ignition near switch and 200/61.54.ccls.	USPAT; US-PGPUB	2003/08/25 00:54
-	1	"3192395".PN.	USPAT	2003/08/25 00:44
-	1	"3145700".PN.	USPAT	2003/08/25 00:45
-	1	"1213811".PN.	USPAT	2003/12/16 22:48
-	1	"1126262".PN.	USPAT	2003/08/25 00:46
-	30	steering near column with ignition near switch and 180/287.ccls.	USPAT; US-PGPUB	2003/08/25 00:52
-	5	"4313520"	USPAT; US-PGPUB	2003/08/25 00:52
-	110	ignition near switch\$2 with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/08/25 09:25
-	1	ignition near switches with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/08/25 09:25
-	108	ignition near switch with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/08/25 09:22
-	17	ignition near switch with (mounted or located) with (panel or dashboard) and 200/\$.ccls.	USPAT; US-PGPUB	2003/08/25 01:07
-	108	ignition near switch with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/08/25 09:22
-	110	ignition near switch\$2 with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/08/25 09:25
-	3	("3938613" "4313520" "5810183").PN.	USPAT; US-PGPUB	2003/12/16 21:56
-	1	3,916,658.PN.	USPAT; US-PGPUB	2003/12/16 21:57
-	774	ignition near switch same (panel or dashboard)	USPAT; US-PGPUB	2003/12/16 22:03
-	364	ignition near switch with (panel or dashboard)	USPAT; US-PGPUB	2003/12/16 22:04

-	112	ignition near switch with (mounted or located) with (panel or dashboard)	USPAT; US-PGPUB	2003/12/16 22:05
-	40	ignition near switch with (mounted or located) near (panel or dashboard)	USPAT; US-PGPUB	2003/12/16 22:06
-	11	ignition near switch near (mounted or located) near (panel or dashboard)	USPAT; US-PGPUB	2003/12/16 22:36
-	12	"3938613"	USPAT; US-PGPUB	2003/12/16 22:38
-	0	(rotatable near collar) same switch same (left near hand near position) same (right near hand near position)	USPAT	2003/12/16 22:50
-	0	(rotatable near collar) same switch and (left near hand near position) and (right near hand near position)	USPAT	2003/12/16 22:50
-	26	(rotatable near collar) same switch	USPAT	2003/12/16 22:51
-	2003	((left near hand near position) and (right near hand near position))	USPAT	2003/12/16 22:51
-	0	((rotatable near collar) same switch) and ((left near hand near position) and (right near hand near position))	USPAT	2003/12/16 22:51
-	2231	((left near hand near position) and (right near hand near position))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:52
-	1	((left near hand near position) and (right near hand near position)) and ((rotatable near collar) same switch)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:52
-	34	(rotatable near collar) same switch	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:55
-	1	(rotatable near collar) same ignition near switch	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:53
-	160079	left near hand	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:56
-	6662	right near hand same panel	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:57
-	3311	((left near hand) same (right near hand same panel))	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:57
-	3311	left near hand same right near hand same panel	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:58
-	5	left near hand same right near hand same panel same ignition near switch	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/12/16 22:58
-	4597	200/61.54.ccls or 307/10.1-10.8.ccls. or 180/287.ccls.	USPAT; US-PGPUB	2003/12/16 23:24
-	336	steering near column same ignition near switch	USPAT; US-PGPUB	2003/12/16 23:25
-	82	((200/61.54.ccls or 307/10.1-10.8.ccls. or 180/287.ccls.) and (steering near column same ignition near switch))	USPAT; US-PGPUB	2003/12/16 23:26
-	84239	((left near hand) same (right near hand))	USPAT; US-PGPUB	2003/12/16 23:27
-	98	((200/61.54.ccls or 307/10.1-10.8.ccls. or 180/287.ccls.) and ((left near hand) same (right near hand)))	USPAT; US-PGPUB	2003/12/16 23:28
-	0	((200/61.54.ccls or 307/10.1-10.8.ccls. or 180/287.ccls.) and ((left near hand) same (right near hand))) and (steering near column same ignition near switch)	USPAT; US-PGPUB	2003/12/16 23:28
-	9	((200/61.54.ccls or 307/10.1-10.8.ccls. or 180/287.ccls.) and ((left near hand) same (right near hand))) and panel and ignition near switch	USPAT; US-PGPUB	2003/12/16 23:28

-	0	ignition near switches with parallel with (panel or board)	USPAT;	2003/12/17 18:18
-	614477	(panel or dashboard or board)	US-PGPUB	2003/12/17 18:18
-	9	(ignition near switches with parallel) and ((panel or dashboard or board))	USPAT;	2003/12/17 18:18
-	1	(ignition near switches with parallel) same ((panel or dashboard or board))	US-PGPUB	2003/12/17 18:18
-	16	ignition near switches with parallel	USPAT;	2003/12/17 18:21
-	731	180/90.CCLS.	US-PGPUB	2003/12/17 18:53
-	0	180/90.CCLS. AND DASHBOARD AND IGNITION ADJ SWITCHES	USPAT;	2003/12/17 18:54
-	0	180/90.CCLS. AND DASHBOARD AND IGNITION NEAR SWITCHES	US-PGPUB	2003/12/17 18:54
-	11	180/90.CCLS. AND DASHBOARD SAME SWITCHES	USPAT;	2003/12/17 18:57
-	4	"5224751"	US-PGPUB	2003/12/17 19:01
-	1	"2436153".PN.	USPAT;	2003/12/17 18:58
-	1	"2818933".PN.	USPAT	2003/12/17 18:58
-	1	"2841233".PN.	USPAT	2003/12/17 18:58
-	395	180/315.CCLS.	USPAT;	2003/12/17 19:01
-	40	180/315.CCLS. AND SWITCHES	US-PGPUB	2003/12/17 19:03
-	1	180/315.CCLS. AND SWITCHES NEAR IGNITION	USPAT;	2003/12/17 19:21
-	1009	180/315,333.CCLS. or 296/90.ccls. or 200/61.85.ccls.	US-PGPUB	2003/12/17 19:22
-	467	SWITCHES NEAR IGNITION	USPAT;	2003/12/17 19:23
-	2	(180/315,333.CCLS. or 296/90.ccls. or 200/61.85.ccls.) and (SWITCHES NEAR IGNITION)	US-PGPUB	2003/12/17 19:23